

## Contents

Synopsis.....	1
<b>1 Factual Information .....</b>	<b>3</b>
1.1 History of the flight.....	3
1.2 Injuries to persons .....	4
1.3 Damage to the aircraft.....	4
1.4 Other damage .....	6
1.5 Personnel Information.....	6
1.5.1 Commander.....	6
1.5.2 Operating First Officer.....	7
1.5.3 Relief First Officer .....	7
1.6 Aircraft Information.....	8
1.6.1 General information.....	8
1.6.2 Aircraft maintenance history .....	8
1.6.3 Insulation blanket specification and maintenance .....	9
1.6.4 Smoke detection and cooling system in the MEC .....	10
1.6.5 Boeing 777 electrical power distribution and control system.....	10
1.6.5.1 Contactor control .....	12
1.6.5.2 Power transfers .....	12
1.6.5.3 No-break power transfer (NBPT) .....	12
1.6.6 Boeing 777 electrical power system protection.....	14
1.6.7 Contactor description (model ELM 827-1) .....	16
1.6.8 Electrical system principles of heat and resistance.....	21
1.6.9 General principles of arcing and arcing containment.....	22
1.6.10 Number of contactor cycles per flight.....	23
1.6.11 Differences between ELMS 1 and ELMS 2 power panels .....	23
1.7 Meteorological information .....	24
1.8 Aids to navigation .....	24
1.9 Communications .....	24
1.10 Aerodrome Information .....	24
1.11 Flight recorders .....	24
1.11.1 General.....	24
1.11.2 Flight recorder operation .....	25
1.11.3 CVR installation .....	25
1.11.4 FDR electrical system parameters .....	25
1.11.5 FDR warning parameters .....	26

1.11.6	Recorded fault messages from GCUs and BPCU.....	26
1.11.7	Summary of relevant data recorded during the event.....	28
1.11.8	Data prior to the event .....	31
1.12	Aircraft examination.....	31
1.12.1	General aircraft examination .....	31
1.12.2	Structural damage examination .....	33
1.12.3	Wiring damage examination.....	34
1.12.4	Insulation blanket examination.....	35
1.12.5	P200 power panel examination.....	38
1.12.6	Examination of Generator Control Units.....	38
1.12.7	Examination of the failed contactors .....	40
1.12.7.1	RGCB contactor examination.....	40
1.12.7.2	RBTB contactor examination .....	42
1.13	Medical and pathological information.....	44
1.14	Fire.....	44
1.14.1	Response by the airport fire service to the accident.....	44
1.14.2	Fire damage.....	45
1.15	Survival aspects.....	45
1.16	Tests and research .....	45
1.16.1	Overview.....	45
1.16.2	Tests of the insulation blanket material .....	45
1.16.3	Other Boeing 777 contactor and power panel failure incidents....	48
1.16.3.1	Failures involving ELMS 2 power panels .....	48
1.16.3.2	Failures involving ELMS 1 power panels .....	52
1.16.4	Examination of failed contactor from A6-EBF incident in August 2006.....	52
1.16.5	Examination of a sample of high cycle/ high time contactors from the fleet.....	53
1.16.5.1	Examination of LBTB, LGCB and APB from N786UA .....	59
1.16.5.2	Examination by ERA of a high time/ high cycle contactor.....	59
1.16.6	Endurance test of an instrumented contactor.....	60
1.16.7	Fault testing of a contactor.....	63
1.16.8	Examination of previous contactor manufacturing quality issues...	64
1.16.9	Power transfer ground test results.....	65
1.16.10	Contactor insulating material properties.....	65
1.17	Organisational and management information.....	67

1.18	Additional information.....	67
1.18.1	Flight crew checklists .....	67
1.18.2	Consequences of the N786UA failure condition occurring in flight.....	68
1.18.3	Probability of the N786UA failure condition occurring in flight... 68	
1.18.4	Safety action taken.....	69
1.18.4.1	Safety action taken by the aircraft manufacturer .....	69
1.18.4.2	Containment tray modification .....	71
1.18.4.3	Implementation of a flight deck smoke warning.....	74
1.18.4.4	Safety action taken by the contactor manufacturer .....	74
<b>2</b>	<b>Analysis.....</b>	<b>79</b>
2.1	Electrical failure event sequence.....	79
2.2	Electrical system protection .....	81
2.3	Possible causes of contactor failure .....	82
2.3.1	Heat-related possible causes of contactor failure .....	83
2.3.2	Non-heat-related possible causes of contactor failure .....	85
2.3.3	Summary of possible causes of contactor failure .....	89
2.4	Probable cause of previous power panel failures.....	91
2.5	Fire and smoke in the Main Equipment Centre .....	92
2.5.1	Effectiveness of the fire retardant insulation blankets .....	92
2.5.2	Flight crew awareness of smoke in the MEC .....	92
2.5.3	Containing and preventing fire in the MEC.....	93
2.6	Action to prevent future recurrence .....	95
<b>3</b>	<b>Conclusions .....</b>	<b>97</b>
3.1	Findings.....	97
3.2	Causal factors.....	99
<b>4</b>	<b>Safety Recommendations.....</b>	<b>100</b>

## Appendices

<b>Appendix A</b>	Boeing 777 Electrical Power System Schematic
<b>Appendix B</b>	NBPT timeline diagram
<b>Appendix C</b>	Analysis of NVM fault messages
<b>Appendix D</b>	Timeline of relevant events from CVR, FDR and NVM data
<b>Appendix E</b>	Results from insulation blanket tests
<b>Appendix F</b>	Tyco report on endurance contactor test