

Contents

Glossary of abbreviations used in this report	(xi)
Synopsis	1
1.1 History of flight	3
1.1.1 Background.....	3
1.1.2 Facility Descriptions	3
1.1.3 Route details	3
1.1.4 Conduct of the flight	4
1.1.5 Offshore witness information	5
1.2 Injuries to persons.....	6
1.3 Damage to the aircraft	6
1.4 Other damage.....	6
1.5 Personnel Information	6
1.5.1 Commander.....	6
1.5.2 Co-pilot	7
1.6 Aircraft Information.....	7
1.6.1 General information.....	7
1.6.2 S-76 helicopter description	8
1.6.3 Main rotor blade description.....	9
1.6.4 Details for the yellow colour-coded main rotor blade	11
1.6.5 Main rotor blade manufacturing process	11
1.6.6 Main rotor blade maintenance requirements	12
1.6.6.1 Manufacturer's routine inspection requirements.....	12
1.6.6.2 Manufacturer's special inspection and repair requirements.....	12
1.6.6.2.1 Cracks in the leading edge erosion cover.....	13
1.6.6.2.2 Scarf joint patch	14
1.6.6.2.3 Post lightning strike inspections	14
1.6.6.2.4 Alert Service Bulletins and Customer Service Notices .	14
1.6.6.3 FAA mandatory inspection requirements.....	14
1.6.6.4 Operator's inspection requirements	14
1.6.7 Main rotor blade, colour-coded yellow, maintenance history	15
1.6.8 Lightning damage to main rotor blades on G-BHBF.....	16
1.6.9 Lightning damage to subject blade	17

1.6.9.1	Blade inspection in the UK.....	17
1.6.9.2	Blade inspection by the USA Repair Station.....	17
1.6.9.3	Blade inspection by the manufacturer	18
1.6.9.4	Scarf joint damage	18
1.6.10	Blade repairs	18
1.6.11	Blade finishing	18
1.6.12	Rotorcraft weight and balance	20
1.6.13	Recent Flight Activity.....	21
1.6.14	Automatically deployable emergency locator transmitter (ADELT)	21
1.7	Meteorological information	21
1.8	Aids to navigation.....	22
1.9	Communications	22
1.10	Aerodrome Information	22
1.11	Flight recorders.....	23
1.11.1	Introduction.....	23
1.11.2	Recovery of the flight recorders	23
1.11.3	Configuration of the CVFDR.....	23
1.11.4	Replay of the CVFDR.....	24
1.11.5	Interpretation of the recordings.....	24
1.11.6	Archive recordings.....	25
1.11.7	Rotor track and balance (RTB).....	26
1.12	Aircraft accident site, wreckage recovery and examination.....	27
1.12.1	Accident site	27
1.12.2	Wreckage recovery	28
1.12.3	Wreckage examination.....	28
1.12.3.1	General.....	28
1.12.3.2	Metallurgical examination of the yellow colour-coded main rotor blade	28
1.12.3.2.1	Blade spar.....	28
1.12.3.2.2	First fatigue striation count	31
1.12.3.2.3	Second fatigue striation count.....	31
1.12.3.2.4	Crack lengths before flight.....	32
1.12.3.2.5	Main rotor blade leading edge erosion cover.....	33
1.12.3.2.6	Internal inspection of main rotor blade spar	34

1.12.3.3 ADELT	34
1.13 Medical and pathological information.....	35
1.14 Fire.....	35
1.15 Survival aspects	35
1.15.1 Search and Rescue	35
1.16 Tests and research.....	36
1.16.1 Crack relationship testing	36
1.16.2 Main rotor blade tip droop.....	37
1.16.3 The fatigue implications of the manufacturing anomaly.....	38
1.16.4 Titanium thermal discoloration.....	38
1.16.5 Fatigue spectrum.....	39
1.17 Organisational and management information.....	39
1.17.1 Flight planning.....	39
1.17.2 Flight-following.....	39
1.18 Additional Information	40
1.18.1 Operating regime of G-BJVX.....	40
1.18.2 Fatigue crack characteristics.....	41
1.18.3 Non-destructive inspection techniques	42
1.18.3.1 Eddy current.....	42
1.18.3.2 Ultra sonic.....	42
1.18.3.3 Radiography.....	43
1.18.3.3.1 X-ray photography	43
1.18.3.3.2 Fluoroscopy.....	43
1.18.3.4 Non-destructive testing resource implications	43
1.18.4 Blade Inspection Method (BIM).....	43
1.18.5 Safety Actions taken	44
1.18.5.1 Initial safety action by the helicopter manufacturer	44
1.18.5.2 Further safety action taken by the helicopter manufacturer	44
1.18.5.3 Safety action by the helicopter operator	45
1.18.6 Main rotor out-of-balance forces	45
1.18.7 Previous titanium main rotor spar failures and spar cracking	45
1.18.8 Total service life of Sikorsky titanium spared main rotor blades	46
1.18.9 Previous folded tang on the titanium erosion cover	46

2 Analysis	47
2.1 Catastrophic failure.....	47
2.2 Scope of analysis	48
2.3 Interim Safety Action	49
2.4 The manufacturing anomaly	50
2.4.1 Blade manufacture	50
2.4.2 Other folded tangs.....	51
2.4.3 Airworthiness of the yellow blade	52
2.5 Thermal damage to the spar.....	52
2.5.1 Lightning strike examinations	52
2.5.2 Detection of thermal damage.....	53
2.5.3 Blade refurbishment.....	54
2.6 Fatigue crack formation	55
2.6.1 Crack initiation	55
2.6.2 Spar crack striation counts.....	56
2.6.3 Fracture mechanics assumptions	57
2.6.4 Spar crack progression during final flight	58
2.6.5 Total time for spar crack propagation.....	59
2.6.6 Crack growth rate shortly before the accident	59
2.6.7 The period between formation of a sympathetic crack and blade failure.....	61
2.6.8 External crack growth.....	61
2.7 Crack detection	61
2.7.1 Detection opportunities.....	61
2.7.2 Crack detection by routine visual inspection.....	62
2.7.3 Crack detection through blade droop or discontinuity	63
2.7.4 The visibility of an external skin crack.....	63
2.7.5 Crack detection by NDT	64
2.8 Protective patches.....	65
2.8.1 The significance of a crack in an erosion cover.....	66
2.8.2 Patch material	66
2.9 Pre-flight inspections.....	67
2.10 Crack detection by onboard technology	68
2.10.1 Flight data recording.....	68
2.10.1.1 Conventional flight data	68

2.10.1.2 Rotor Track and Balance Data limitations.....	69
2.10.1.3 Rotor tracking vibration.....	69
2.10.1.4 General vibration data.....	70
2.10.1.5 Exceedence warnings.....	70
2.10.1.6 Track, lag and velocity trends.....	71
2.10.2 Crack detection using the BIM system.....	71
2.11 Noises and vibrations in flight.....	71
2.12 Flight crew's response to increased vibration.....	72
2.13 The final events.....	73
2.14 Rotor tracking vibration.....	73
2.15 Modifications to the blade design.....	74
2.15.1 Retrospective fitting of the BIM system.....	74
2.15.2 Future blade designs	74
2.16 Probability of a recurrence	75
2.17 Safety actions taken	76
2.18 Search and Rescue	77
2.18.1 ADELT	77
2.18.2 Unexpected arrival of G-BJVX	77
2.18.3 Flight-following.....	78
3 Conclusions	80
(a) Findings	80
(b) Causal factors.....	83
4 Safety Recommendations	84

ANNEXES

- A Route flown by G-BJVX during accident flight
- B Extract from Pilot's Preflight Check
- C Extract from Composite Materials Manual
- D Engineering Instruction E76-762-10-1331 - Recommended Post Lightning Strike
Inspection for Main and Tail Rotor Blades
- E History of the Yellow Colour-Coded Main Rotor Blade
- F G-BJVX - Recent Flight Activity
- G Data Frame Layout
- H Variation in Signal Levels During Final 0.75 Seconds of Cockpit Voice Recording
- I Time History of CVFDR Parameters
- J How a Rotor Tracker Works
- K Extract from Flight Data Services Limited Report
- L Diagrams showing Wreckage Location
- M Extract from QinetiQ Limited Report
- N Crack Progression Data (QinetiQ Data)
- O Extract from Sikorsky Striation Count Document
- P Sikorsky S76 Main Rotor Blade Failure - Striation Data Analysis
- Q Sikorsky S76 Main Rotor Blade Erosion Strip Analysis
- R Sikorsky S76 Main Rotor Blade Failure